Waterloo Water Works, Well House 4 (Cedar Park Restroom) Fairview and Lafayette Avenues Waterloo Black Hawk County Iowa

HABS No. IA-125

HABS IOWA, T-WATLO,

PHOTOCRAPHS

REDUCED COPIES OF MEASURED DRAWINGS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

Form 10-920 (June 1983)

Historic American Buildings Survey UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS 10WA, 7-WATLO, 3-

ARCHITECTURAL DATA FORM

OT ATE	COLINITY		TOWN OR VIC	ZINITV	
STATE					
	·		Wate	rloo	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)				HABS NO.	
Waterloo Water Works, Well House 4			IA-125		
SE CON DARY OR COMMON NAMES OF S	STRUCTURE				
Cedar Park Restroom					
COMPLETE AODRESS (DESCRIBE LOCA	TION FOR RURAL	SITES)			
Fairview and Lafayette Avenues	s				
DATE OF CONSTRUCTION (INCLUDE SOURCE) ARCHITECT(S) (A		ARCHITECT(S) (INCL	.UDE SOURCE,)	
1914		Mortimer Cleveland, Sr.			
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)					
This structure serves as a fur park setting.	nctional elemen	nt treated as a d	ecorative	pavilion in a	
STYLE (IF APPROPRIATE)			**************************************		
MATERIAL OF CONSTRUCTION (INCLU Two colored brick walls suppor divider of the two restrooms.			cinder blo	ck wall was added as a	
CHAPE AND OIMENSIONS OF STRUCTU	RE (SKETCHED FL	OOR PLANS ON SEPAR	ATE PAGES A	RE ACCEPTABLE)	
EXTERIOR FEATURES OF NOTE Fach facedo of the lower story is distill the st.					
raised brick bands of color darker than that of the panels contained therein. The rhythm					
thus created is set against the rafters which divide the open eaves into eight intervals.					
The upper portion sits in the center of the structure with shorter eaves & more highly					
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) patterned brickwork.					
MAJOR ALTERATIONS AND ADDITIONS WITH OATES					
In 1932 the well was shut down this time the tower was remove	and in 1962 to and the eave	the building was shortened.	turned into	o a restroom. At	
PRESENT CONDITION AND USE			7		
Demolished, Fall 1978					
OTHER INFORMATION AS APPROPRIAT the U.S. Army Corps of Engine of Agreement with the Advisory	ers in complia Council on Hi	storic Preservat	ve Order 11 ion.	1593 and a Memorandum	
Sheet No. 4 of the measured drawings is the first scaled rectified photo drawing in the					
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)					
COMPILER, AFFILIATION Sarah Deni	net , Hans Mue	ssig, Consultant:	3	DATE	
R. Lange, M. McDonald, HABS			6-13-84		